



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/14/17


Del Mar Union School District
Ashley Falls Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1174609	06/02/17	06:32 AM	SAMPLE 1	3710020-CBG-A	< 5	ug/L
W1174610	06/02/17	06:35 AM	SAMPLE 2	3710020-CBG-B	< 5	ug/L
W1174611	06/02/17	06:37 AM	SAMPLE 3	3710020-CBG-C	< 5	ug/L
W1174612	06/02/17	06:40 AM	SAMPLE 4	3710020-CBG-D	< 5	ug/L
W1174613	06/02/17	06:42 AM	SAMPLE 5	3710020-CBG-E	< 5	ug/L

Source Source Description

- SAMPLE 1 MUR, Behind boy's restroom, two single bubbler fountains, lower right fountain
- SAMPLE 2 East side of 400 wing in between boys / girls upper grade RRs, two single bubbler fountains, lower right fountain
- SAMPLE 3 Classroom 605, Bottom of two story building right side, bubbler at sink
- SAMPLE 4 west end of 400 building, two single bubbler fountains, upper right fountain
- SAMPLE 5 Wing 300, Interior hallway across classroom 305, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist