



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/14/17

Del Mar Union School District
Del Mar Heights Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1174619	06/01/17	06:36 AM	SAMPLE 1	3710020-CBI-A	< 5	ug/L
W1174620	06/01/17	06:40 AM	SAMPLE 2	3710020-CBI-B	< 5	ug/L
W1174621	06/01/17	06:42 AM	SAMPLE 3	3710020-CBI-C	< 5	ug/L
W1174622	06/01/17	06:45 AM	SAMPLE 4	3710020-CBI-D	< 5	ug/L
W1174623	06/01/17	06:47 AM	SAMPLE 5	3710020-CBI-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 East playground Area, In between Girls / Boys lower grade RRs, two single bubbler fountains on pedistal, lower left fountain when facing palm trees
- SAMPLE 2 D building, West side of D building in between boys / girls upper grade RRs, two single bubbler fountains, upper right fountain
- SAMPLE 3 D building, Classroom D-3 back corner of room, bubbler at sink
- SAMPLE 4 west end of C-wing, dual bubbler fountain, right bubbler
- SAMPLE 5 A Building, Classroom A-1, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist