



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/14/17

Del Mar Union School District
Ocean Air

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1175399	06/06/17	06:32 AM	SAMPLE 1	3710020-CCA-A	< 5	ug/L
W1175400	06/06/17	06:34 AM	SAMPLE 2	3710020-CCA-B	< 5	ug/L
W1175401	06/06/17	06:38 AM	SAMPLE 3	3710020-CCA-C	< 5	ug/L
W1175402	06/06/17	06:40 AM	SAMPLE 4	3710020-CCA-D	< 5	ug/L
W1175403	06/06/17	06:43 AM	SAMPLE 5	3710020-CCA-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	South end of 300 wing, two single bubbler fountains, lower right fountain
SAMPLE 2	600 wing, Classroom 601, bubbler at sink
SAMPLE 3	Behind 400 wing in between boys / girls RRs, two single bubbler fountains, upper left fountain
SAMPLE 4	Classroom 701, bubbler at sink
SAMPLE 5	Behind MUR right side, two single bubbler fountains, upper left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist